



## CHUBBY CHEEK NURSERY

Vehicle Running Report for the date 2021-09-17

SL NO	Vehicle Number/Name	Driver Name	Vehicle IMEI	First Ignition	Last Ignition	Total Engine ON Time
1	AD-1-87470-MITSUBISHI ROSA		867604055799531	10:22:26	16:17:17	00:01:55
2	AD-2-85577-MITSUBISHI ROSA		867604055806815	06:20:21	18:23:44	00:34:47