



CHUBBY CHEEK NURSERY

Vehicle Running Report for the date 2021-09-15

SL NO	Vehicle Number/Name	Driver Name	Vehicle IMEI	First Ignition	Last Ignition	Total Engine ON Time
1	AD-1-87470-MITSUBISHI ROSA		867604055799531	06:36:26	15:26:57	05:04:10
2	AD-2-85577-MITSUBISHI ROSA		867604055806815	03:55:57	21:55:49	05:04:03
3	AD-1-73769-MITSUBISHI ROSA		867604055817515	06:06:26	20:51:06	07:51:08