



CHUBBY CHEEK NURSERY

Vehicle Running Report for the date 2021-08-04

SL NO	Vehicle Number/Name	Driver Name	Vehicle IMEI	First Ignition	Last Ignition	Total Engine ON Time
1	AD-1-87470-MITSUBISHI ROSA		867604055799531	05:15:47	17:51:43	03:42:53
2	AD-2-85577-MITSUBISHI ROSA		867604055806815	00:00:45	23:46:33	09:44:59
3	AD-1-73769-MITSUBISHI ROSA		867604055817515	06:07:39	16:59:07	06:03:31